


# Capabilities Statement Cultural

www.vertical-access.com





### **BUSINESS + CONTACT INFO**

### **NAICS CODES**

238190 Other Structure, and Building Exterior

Contractors

541310 Architectural Services

541330 Engineering Services

541350 Building Inspection Services

541690 Other Technical Consulting Services

### **PSC CODES**

C213 A/E Inspect - Non Construct

H399 Inspect Svcs

H999 Misc Test and Inspect Svcs

R425 Engineering and Technical Services

R499 Other Professional Services

Z1 Maint-Alt-Rep, Buildings

### **BUSINESS CLASSIFICATION**

Small Business - incorporated in 1998 in New York

TIN / EIN 16-1569768

DUNS 077311459

CAGE code 332D9

### **KEY CONTACT**

Kent Diebolt, Founding Partner 607-257-4049 office | 607-227-3366 mobile kent@vertical-access.com

### MAIN MAILING ADDRESS

PO Box 4135, Ithaca, NY 14852

### PHYSICAL OFFICE LOCATIONS

369 Asbury Road, Freeville, NY 13068
32 Old Slip, 10th Floor, New York, NY 10005
1053 31st St NW, 2nd Floor, Washington, DC 20006
196 Whitfield St, Guilford, CT 06437
234 E. 100 S., C2, Salt Lake City, UT 84111

### SPECIALIZED SERVICES

#### **PROFESSIONAL SERVICES**

- Existing conditions documentation
- Industrial rope access SPRAT certified
- Difficult access consulting
- Monitoring instrumentation installation
- Live-feed video

### NONDESTRUCTIVE TESTING SERVICES

- Infrared thermography
- Ultrasonics
- Borescope investigations
- Rebar location
- In situ materials sampling and characterization

### REFERENCES

### **Steven Warsavage**

Associate Director of Construction American Museum of Natural History Central Park West at 79th Street New York, NY 10024 (212) 769-5552

swarsavage@amnh.org


### **Tom Scally**

Building Manager
The Metropolitan Museum of Art
1000 Fifth Avenue
New York, NY 10028
Tom.Scally@metmuseum.org

### VERTICAL ACCESS LLC - FIRM OVERVIEW

Vertical Access LLC is a qualified small business that performs specialized inspection services on buildings, monuments, sculptures and civil structures. We are contracted

by architects and engineers nationwide for our expertise in construction technologies, materials science, structural engineering, historic preservation, architectural conservation, and fall protection systems evaluation.



- Civil Structures: bridges, dams, infrastructure
- Towers, smokestacks, monuments and sculptures

We use direct-to-digital software, TPAS® (Tablet PC Annotation System) for inspections. This system was developed specifically for the building industry and allows our technicians to input graphical and numerical conditions data and photos directly into AutoCAD drawings.









### CORE COMPETENCIES

### Industrial rope access systems used for:

- Existing conditions surveys
- Facade ordinance inspections
- Due diligence and prepurchase real estate inspections
- Access consulting

### Certified

All rope technicians third-party certified by SPRAT, the Society of Professional Rope Technicians

### Nondestructive testing and monitoring services

- Infrared thermography
- Ultrasonics
- Optical device investigations
- Wall tie and rebar location
- In situ materials sampling and characterization
- Monitoring instrumentation installation

### Government agency regulations and protocols

- Experienced with working on federal and state agency projects
- Staff holds current security clearance with Department of Homeland Security

### Site specific safety plans

- Hazard analysis
- Fall protection systems
- Emergency rescue plans for VA personnel

### Direct-to-digital documentation

- Vertical Access has developed a system of collecting survey data while working at-height called TPAS® (Tablet PC Annotation System) http://www.tpasllc.com
- AutoCAD drawings are annotated with conditions data in the field using tablet computers

### Deliverables

- Assessment report with images and narratives
- Annotated AutoCAD drawings (print and digital)
- Spreadsheets of extracted data with quantities
- Photographs of conditiona anomalies keyed to drawings
- Video documentation (high definition video from hand-held or helmet mounted camera)
- Cost estimates and recommendations
- Project website to view and share annotated drawings, photographs and quantities

# VERTICAL access

## RELEVANT PROFESSIONAL AFFILIATIONS

Society of Professional Rope Access Technicians SPRAT

Structural Engineers
Association of New York

International Concrete Restoration Institute

ANSI - Z359 Fall Protection Committee Members

American Society of Civil Engineers

American Society of Safety Engineers

National Council of Structural Engineers Associations

Association of State Dam Safety Officers

Construction History Society of America

The Masonry Society

New York Landmarks Conservancy

Society for Industrial Archeology

### PROJECT PROFILES

### Metropolitan Museum of Art Sackler Gallery New York, NY

Client: Metropolitan Museum of Art

### **Scope of Work**

- Designed and installed netting mock-up below sky light immediately following request by building owner.
- Completed netting installation covering 20,000 square feet within two weeks of initial call.



### American Museum of Natural History Rose Center for Earth and Space New York, NY

Client: American Museum of Natural History

### **Scope of Work**

- Used industrial rope access to perform hands-on investigation and documentation of existing conditions of ceiling panels.
- Documented conditions of four model celestial bodies which are hung from the Rose Center's ceiling.



### John G. Shedd Aquarium Chicago, IL

Client: Klein & Hoffman, Inc

### **Scope of Work**

- Close visual examination and hammersounding of masonry at exterior faces.
- Documentation of fault conditions to assist project team with development of repair specifications.
- Provided training and guiding of project client to perform hands-on inspection of representative areas of facades.





### PROJECT PROFILES

### New York Botanical Garden Brooklyn, NY

Project Team: Silman; Jan Hird Pokorny Associates, E.W. Howell Company

### **Scope of Work**

- Collaborated with project team to research and analyze access options, choosing a combination of industrial rope access and aerial lift.
- Used electronic calipers and an ultrasonic thickness gauge to provide measurements of section loss due to corrosion at areas unreachable by client.
- Opened probes in wood fascia to document hidden connection details.
- Provided live-feed, high definition video and real-time audio communication with project team on the ground enabling them to see the conditions up-close.



### Philadelphia Museum of Art Philadelphia, PA

Client: Vitetta

### **Scope of Work**

- Provided temporary fall protection to access a series of massive tile roofs.
- Developed scaled and dimensioned partial roof plans for each gutter and measued gutter slope using a laser level.
- Created a series of detailed sections and isometric drawings to document existing gutter, valley and flashing configurations.
- Employed a fiber-optic diagnostic tool (the SeeSnake®) to investigate internal copper leaders and cast iron drains.






### PROJECT PROFILES

### State Museum of Pennsylvania and State Archives, Harrisburg, PA

Project Team: Pennsylvania Historical and Museum Commission, Conservation Solutions, Inc., Reynolds Construction Management

### **Scope of Work**

- Completed comprehensive close visual examination of end wall with minimal impact on building occupants and public.
- Compared findings from current survey to previous survey data using digital documentation.



### United States Capitol Dome Washington, DC

Client: Office of the Architect of the Capitol

### **Scope of Work**

- Hands-on inspection of all projecting ornament at the exterior of the dome from the top of the lantern to the peristyle column capitals.
- Documentation of existing conditions of cast iron ornament.
- Temporary stabilization and waterproofing measures at selected areas of ornament.



### Old Post Office Washington, DC

Project Team: General Services Administration, The Trump Organization, Silman

### **Scope of Work**

- Surveyed and documented existing conditions at exterior of main building and tower.
- Provided live-feed video to project team during inspection
- Mitigated a 150 square-inch hazardous granite spall on the tower exterior and installed a temporary waterproofing repair.

