

## Saint Thomas Church ♦ New York, NY



### Scope of work:

- conducted a close visual inspection of the limestone facade, employing live video feed for interaction with architectural conservators and structural engineers
- conducted a close visual inspection of carved stone reredos, stone groins and associated Guastavino tile vaulted ceilings
- prepared a condition report including text, annotated elevations, video, still photos

### Building description:

Saint Thomas Church was designed by Cram and Goodhue and completed in 1913. The Gothic Revival style structure is clad in limestone and features elaborate reredos designed by sculptor Lee Lawrie.

### Building owner:

St. Thomas Church

### In collaboration with:

- Beyer Blinder Belle
- Robert Silman Associates



*Photos by Jon Reis/Photolink*